The Dodge/MB fuel filter Water-in-Fuel (WIF) drain tube had a real flimsy clip on the sensor end. It was a white clip and the "ears" on both sides, that tended to snap the first, or second time it was used... once damaged, you had to replace the entire hose to a cost of \$50 to \$80... There is a real simple \$3 fix for this...



The is the damaged part...



this is the dimensions to bend the plate (a 1-1/2'' strap plate)



Here is what it looks like when attached and held in place by one of the screws on the WIF sensor.